



A diagram showing the assembly being pulled out. A curved arrow points from the top of the assembly to the left, indicating the pull-out direction. Below the assembly, a thick black arrow points to the right, labeled "PULL OUT DIRECTION(PLATED)". To the right of the label is a small triangle with the number "1" inside it.

RoHS Compliant

4				CVILUX CORP 2015.07.02 ISSUED			DATE	UNIT: mm / inch		TITLE: BOARD IN TERMINAL	 瀚荃股份有限公司 CviLux Corporation			
3					DRAWN BY:	Karen	6/22-15'	TOLERANCE UNLESS OTHERWISE SPECIFIED				MATERIAL:		
2					ENGINEER:	Sun	6/23-15'	.X ± 0.20 / .008	X" ± 1"	FINISH:				
1	Karen	6/13-15'	ECNT115140/ECRT115017		CHECKED BY:	Eisley	6/23-15'	.XX ± 0.10 / .004	.X" ±				DRAWING NO.	CT0702SB
SYM	NAME	DATE	REVISIONS	APPROVED BY:	Eisley	6/23-15'	.XXX ± 0.05 / .002	.XX" ±			SCALE	5 / 1	SHEET	1 OF 1